

 . RV Maintenance Log

- **Purchased Jan 2016**
 - New entry steps installed by dealer
- **Feb 2016**
 - Flushed and cleaned holding tanks
 - Replaced serpentine belt
 - Replaced black water valve
 - Replaced oil cooling lines on engine
 - Replaced cooling fans on front of engine
 - Inspected and sealed roof
- **March 2016**
 - Installed all new tires
 - Replaced missing refrigerator handle
- **May 2016**
 - Installed hitch for towing
 - Exterior waxed
- **July 2016**
 - New starter motor
 - Fuel line repair on generator
 - Replaced gasket seal under toilet
 - Replaced shower faucet
- **Dec 2016**
 - Oil change
 - Generator service
 - Replaced engine knock sensors
 - Installed fans in fridge stack
 - Awning maintenance
 - Tightened fittings for fridge, ensured draining properly
 - Replaced front rotors and pads
 - Repair hub leak front driver side
- **January 2017**
 - Replaced slideout control board
 - Replaced house battery
- **March 2017**
 - Inspected and sealed roof
 - Sealed along awning rail with tape
 - Replaced rusty screws on exterior body
 - Conditioned rubber seals around slides
- **May 2017**
 - Installed new Koni FSD shocks
 - Had the front tires aligned, balanced and trued
 - Replaced rear television
- **July 2017**
 - Replaced slide toppers
 - Flushed water heater
 - Cleaned roof AC units
- **August 2017**
 - Replaced right-side exhaust manifold donut gasket
 - Tune up (new spark plugs and wires)
 - Replaced Ventline fan blade in bathroom
 - Sealed bottom of shower enclosure with caulk
 - Replaced kitchen faucet

- Replaced bathroom faucet
- Replaced all cabinet and door handles
- **September 2017**
 - Replaced Holiday Rambler decal on front grill
- **December 2017**
 - Replaced mattress
 - Replaced gasket around doghouse
 - Replaced part of gasket seal in basement door, slide out.
 - Oil change. 43292 odometer.
 - Installed Roadmaster rear anti-sway bar
 - Installed Safe-t-Plus steering stabilizer
 - Replaced both A/C shrouds and installed new filters
- **January 2018**
 - Replaced 2 glass panes which were fogged
 - Installed rock guard brush on rear bumper
- **February 2018**
 - Replaced main awning
 - Fix 3 brass reading lights so they all work
 - Replace front headlights (one had water in it)
 - Paint above awning to make it look better
 - Replace fridge vent cover
 - Reseal shower skylight
- **March 2018**
 - Generator oil change 866 hours
 - Replaced several bulbs, including rear brake light
 - Caulk shower, reseal cold water connection on shower faucet
- **April 2018**
 - Pulled up all carpet, laminate wood flooring in preparation for new flooring
 - Repaired few areas of rotted subfloor.
 - Fixed cruise control by adjusting brake light switch
 - Built stand to help support weight of washer/dryer
- **May 2018**
 - Polyurethane coating on subfloor (2 coats)
 - Installed vinyl plank flooring, trim molding
 - Installed new carpet
 - Repair loose ladder, broken supports
- **June 2018**
 - Repaired side panel fiberglass damage over rear wheel
 - Installed new furniture
 - Installed new carpet binding on the slideout.
- **July 2018**
 - Buffed out oxidation from exterior fiberglass
 - Transmission fluid change (46,700 miles)
 - Oil Change
 - Wired fans in fridge stack with manual switch
 - Changed air filter to NAPA Gold 6316 - 49,003 miles
 - Removed and cleaned MAF Sensor - 49,003 miles
- **August 2018**
 - Replaced fuel filter. 49,500 miles
 - Replaced generator fuel pump, fuel filter. - 900 hours
- **December 2018**
 - Oil change
 - Replaced chassis battery
- **March 2019**

- Replace outer hub gaskets, rear, both sides
- Top off differential fluid
- **May 2019**
 - Change out the washer/dryer with a Splendide 2100XC
- **July 2019**
 - Buff exterior fiberglass
 - Replace convex mirror, passenger side mirror (bottom)
 - Replaced passenger side brake light bulb
 - Removed main slide topper (to be replaced with new version). Both springs were snapped.
- **August 2019**
 - Replaced motor in entry steps
 - Replaced turning signal bulb, driver side
 - Flushed water heater
- **February 2020**
 - Change oil on generator (965 hours)
 - Top off fluid in leveler system
 - Permanent install of Weboost Cell Signal Booster
- **June 2020**
 - Install new slide-topper on main slideout
 - Greased the entry steps
- **July 2020**
 - Replaced backup camera monitor in dashboard
- **October 2020**
 - Repaint the roof with Rustoleum marine topside.
 - Replaced leaky fuel line into generator
 - Installed SumoSprings front
 - Repaired compartment door handle, passenger side, rear
- **November 2020**
 - Replaced rubber seal around window on entry door
 - Replaced fuel line into engine (it began leaking). Makeshift line, not same as original.
- **December 2020**
 - Replaced water pump
 - Replaced converter
 - Replaced cooling unit on Norcold refrigerator with HVAC 12V system from JC Refrigeration
 - Replaced bed gas struts
 - Fixed opening mechanism on Fan-tastic roof fan
 - Fixed collapsed floor shelf under laundry
 - Replaced all 6 speakers
 - Replace dash stereo with new one that has USB and Bluetooth
- **February 2021**
 - Oil change - 60,264 miles - Full synthetic 5W30
 - PF454 filter ACDelco
 - 15mm drain plug
- **March 2021**
 - Wash and some buffing of oxidation (but need to do it again, since it didn't come out very well)
- **April 2021**
 - Replaced fuel line with steel braided, proper fittings (one that was put in in November 2020)
 - Replaced toilet
- **May 2021**
 - Replaced steering stabilizer (Safe T Plus) with new unit to alleviate a squeal. Was a warranty unit.
- **June 2021**
 - Replaced front tv
 - Install tablet mount
 - Replaced stove vent

- Replaced screen door latch
- New A/C filters
- **July 2021**
 - Replaced 3rd rear brake light.
- **August 2021**
 - Replaced spark plugs and wires. New wires are the Magnum Extremes and are supposed to be awesome. :-)
- **May 2022**
 - Replaced entry step motor
- **September 2022**
 - Removed and resealed front driver-side window, above driver door
 - Removed CB radio antenna
 - Removed ice maker
- **May 2023**
 - Replaced mounting flange for toilet
 - Oil change 63320
 - Generator oil change 1000 hours
- **June 2023**
 - Replaced exhaust flange gaskets, driver & passenger sides
 - Replaced exhaust manifold gasket, driver side.
- **September 2023**
 - Replaced gearbox on step (was grinding)
 - Replaced hose attachment and hose to black tank flush in water compartment
 - Replaced step fuses (new motor blew fuses, so replaced in campsite)
- **December 2023**
 - Replaced house battery with Lithium
 - Replaced converter (to be compatible with new battery)
- **January 2024**
 - Replaced interior lights with LEDs
- **May 2024**
 - Replaced belt torsioner
 - Replaced alternator
 - Replaced fridge with Frigidaire residential fridge
 - Replaced closet door latches
- **June 2024**
 - Replaced carburator on generator, oil change
 - Secured driver side front mirror so it won't shake so much
 - Installed wood base behind dump valve plastic panel to keep it from flexing
- **November 2024**
 - Replaced manifold intake gaskets on both sides of the engine
 - Replaced donut gaskets
- **December 2024**
 - Installed new bathroom GFI outlet (old one fried)
 - Installed new chassis battery
 - Oil change 66,407 miles